



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

0002

Inspection Report
Minerals Regulatory Program
Report Date September 26, 2005

Supervisor DRZ

Mine Name: Tumbleweed
Operator Name: Jerry Stocks

Permit number: S/019/056
Inspection Date: August 17,
2005
Time: 6:10-6:20 PM

Inspector(s): Paul Baker
Other Participants: None
Mine Status: Inactive

Weather: Partly cloudy, 90's

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

In light of a release request from the operator, the purpose of the inspection was to see whether the site had been disturbed.

Inspection Summary:

12. Other.

I used the maps furnished by the operator to locate the site, and based on the contours, the alignment of a two-track road, and the proximity to a wash, I feel confident I found the area the operator had intended to mine. There were no signs of any mine-related disturbance.

Conclusions and Recommendations:

I recommend that the reclamation surety be released and the NOI closed.

Inspector's Signature

REB

Date: September 26, 2005

PBB:jb

cc: Jerry Stocks, operator
John Blake, SITLA

O:\M019-Grand\S0190056-Tumbleweed\inspections\ins-08172005.doc

0002